m/023/0/6 Page 1 of 1 1. FOREST USDA - Forest Service Manti-La Sal National F CONTRACT DAILY DIAKY 2. CONTRACT NO. (Reference FSH 6309.11) 3. PROJECT **Gypsum Mines** 5. CONTRACTOR REPRESENTATIVE ON SITE 4. CONTRACTOR None H.E. Davis Construction 6. GOVERNMENT OFFICIALS ON SITE Joel Nowak 8. DAY OF WEEK 9. TIME ARRIVED 10. TIME DEPARTED 11. WEATHER 7 DATE 7/13/2005 1100 Wednesday 1430 Mostly Sunny 15. DAYS USED | 16. COMPLETION DATE 13. GROUND CONDITION 14. CONTRACT TIME 12. TEMPERATURE °F. Dry Max. 85 Min. 75 19. WORK ON SCHEDULE 20. CONTRACTOR'S WORK - (X Appropriate Box) 18. WORK COMPLETED (%) 17. TIME USED (%) ☐ Unacceptable - Explain in narrative ☐ Acceptable □ NO ☐ YES 22. WORK ORDERS ISSUED (Include SUSPEND/RESUME) 21. CHANGE ORDERS/AMENDMENTS ISSUED 24. LIST EQUIPMENT ON SITE (Furnished by G-Govt.; C-Cont.; S-Subcont.) → 23. MATERIALS FURNISHED TO JOB SITE (Furnished By: G-Govt.; C-Cont.; S-Subcont.) > + Hours Used ♦ Contract Item Number and Location of Use Type 25. LIST CONTRACT PAYMENTS, REPORTS, CORRESPONDENCE, ETC. 26. WORKERS ON SITE Number PRIME SUB Classification Submit 27. GOVERNMENT PROVIDED SERVICES ADEQUATELY AND TIMELY ☐ YES ☐ NO - Explain in narrative 28. NARRATIVE REPORT Only one dump truck operating at the time I was inspecting. The pit looked as it did last inspection with a little more mined out from the southeast wall. They were compliant with the Plan of Operations with the exception of the size of the pit (over the acreage limitation, which we are allowing as long as they don't increase it over the current footprint). Also, there were very little signs of benching as they were working further into the deposit. See Photos RECEIVED AUG 2 2 2005 DIV OF OIL GAS & MINING 31. ADDTL SPACE NEEDED 29. SIGNATURE 30. TITLE (continued on 6300-21) Physical Science Technician



HEDavisGypsum29.JPG 7/13/2005 Mill site on private land



HEDavisGypsum30.JPG 7/13/2005 Looking South



HEDavisGypsum110.JPG 7/13/2005 Looking East



HEDavisGypsum20.JPG 7/13/2005 Looking south